

Date: Wednesday, 19/03/2008 11:29:01 AM
User: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : D2746
Job Number : 38111	
Estimate Number : 10804	
P.O. Number :	Part Number : D2746
This Issue : 19/03/2008 S.O. No. :	Drawing Number : R08-017
Prsht Rev. : NC	Project Number :
First Issue : / / Type : SMALL /MED FAB	Drawing Revision :
Previous Run : 00015	Material :
Written By :	Due Date : 26/03/2008 Qty: 2 Um: Each
Checked & Approved By :	
Comment :	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



08-03-19 (2)



Comment: INSPECT WORK TO CURRENT STEP

2.0	D2746	Wearshoe
-----	-------	----------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s)

Wearshoe

Qty 2:

-1 of original B32991

-1 of original B35495

3.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify the 2 with the new batch #, and restock items

Location: *FP 15*

AS 08/03/20

(2)

4.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



(2)

Comment: FINAL INSPECTION/W/O RELEASE

AD 08/03/20

Job Completion



U 08-03-24